PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : 7,719,376 B2

Issue Date : May 18, 2010

Inventors : Alexander Lampe et al.

Docket No. : 853563.431USPC

Date : August 31, 2010

Mail Stop Certificate of Correction Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents:

A certificate of correction is respectfully requested in the above-identified patent. The following error was made:

In the claims, issued claim 6, column 8, line 20, the line "configured to amplify an output of the transmitter." is incorrect. As set forth in the Amendment filed with the U.S. Patent and Trademark Office on September 29, 2009, the correct line should read --a power amplifier configured to amplify an output of the transmitter.--

Issued claim 6 appears as claim 8 during prosecution

Attached is the certificate of correction, which indicates the correction to be made, by reference to the column and line number in the printed patent. Because the error was made by the Patent Office, no fee is necessary. However if the error is determined to be our error, the Director is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 19-1090.

Respectfully submitted,

SEED Intellectual Property Law Group PLLC

/Timothy L. Boller/
Timothy L. Boller
Registration No. 47,435

TLB:tt Enclosure:

Certificate of Correction

SEED Intellectual Property Law Group PLLC 701 Fifth Avenue, Suite 5400 Seattle, Washington 98104-7092 Phone: (206) 622-4900

Fax: (206) 682-6031

1695609_1.DOCX

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

: 7,719,376 B2

DATED

: May 18, 2010

INVENTORS

: Alexander Lampe et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8, Line 20

The line "configured to amplify an output of the transmitter." should read --a power amplifier configured to amplify an output of the transmitter.--

MAILING ADDRESS OF SENDER:

PATENT NO. 7,719,376 B2

Timothy L. Boller Seed Intellectual Property Law Group PLLC 701 Fifth Avenue, Suite 5400 Seattle, Washington 98104

No. of additional copies 0

Burden hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231. 1695614_1.DOCX